

## LEGEND

### Viewshed

- Land Cover Viewshed Area (130ft Tower)  
(Includes existing vegetation and structures)
- Photo Locations

Note: Viewshed areas are not definitive. Viewshed mapping provides a general understanding of where the proposed project is theoretically visible based on regional topographic, forest and building cover data sources.

The "Land Cover" condition viewshed area includes the screening effect of intervening vegetation and buildings. The location and height of vegetated areas and buildings is based on 2016 Lidar data aquired from Connecticut DEEP.




Figure A0  
LAND COVER VIEWSHED MAP - CAMERA LOCATIONS

Visual Resource Assessment  
New York (NY-578)

Wireless Telecommunications Facility

Granite Springs Road  
Yorktown Heights, NY 10598



Photo 1 - Granite Springs Road  
EXISTING CONDITION

Photograph Information

Date: April 16, 2021  
Time: 04:33 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 23.3204" N,  
73° 46' 41.6813" W  
Distance to Tower: 1,050 Feet

Figure B1

PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)



Photo 1 - Granite Springs Road  
PROPOSED CONDITION - 130FT GALVANIZED TOWER

Photograph Information

Date: April 16, 2021  
Time: 04:33 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 23.3204" N,  
73° 46' 41.6813" W  
Distance to Tower: 1,050 Feet

Figure B2

PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)



Photo 1 - Granite Springs Road  
PROPOSED CONDITION - 130FT MONOPINE

Photograph Information

Date: April 16, 2021  
Time: 04:33 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 23.3204" N,  
73° 46' 41.6813" W  
Distance to Tower: 1,050 Feet

Figure B3

PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)



Photo 2 - Granite Springs Road  
EXISTING CONDITION

Photograph Information

Date: April 16, 2021  
Time: 04:39 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 20.5451" N,  
73° 46' 28.3930" W  
Distance to Tower: 700 Feet



Photo 2 - Granite Springs Road  
PROPOSED CONDITION - 130FT GALVANIZED TOWER

Photograph Information

Date: April 16, 2021  
Time: 04:39 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 20.5451" N,  
73° 46' 28.3930" W  
Distance to Tower: 700 Feet



Photo 2 - Granite Springs Road  
PROPOSED CONDITION - 130FT MONOPINE

Photograph Information

Date: April 16, 2021  
Time: 04:39 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 20.5451" N,  
73° 46' 28.3930" W  
Distance to Tower: 700 Feet



Photo 3 - Granite Springs Road near Hilltop Road  
EXISTING CONDITION

Photograph Information

Date: April 16, 2021  
Time: 04:44 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 16.5522" N,  
73° 46' 22.1697" W  
Distance to Tower: 1,220 Feet

Figure B7

PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)

Granite Springs Road

Yorktown Heights, NY 10598



Photo 3 - Granite Springs Road near Hilltop Road  
PROPOSED CONDITION - 130FT GALVANIZED TOWER

Photograph Information

Date: April 16, 2021  
Time: 04:44 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 16.5522" N,  
73° 46' 22.1697" W  
Distance to Tower: 1,220 Feet

Figure B8

PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)



Photo 3 - Granite Springs Road near Hilltop Road  
PROPOSED CONDITION - 130FT MONOPINE

Photograph Information

Date: April 16, 2021  
Time: 04:44 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 16.5522" N,  
73° 46' 22.1697" W  
Distance to Tower: 1,220 Feet



Photo 4 - Granite Springs Road near Hilltop Road, near #54

#### EXISTING CONDITION

#### Photograph Information

Date: April 16, 2021  
Time: 0450 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 23.1983" N,  
73° 46' 34.4618" W  
Distance to Tower: 600 Feet

Figure B10

#### PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)



Photo 4 - Granite Springs Road near Hilltop Road, near #54  
PROPOSED CONDITION - 130FT GALVANIZED TOWER

Photograph Information

Date: April 16, 2021  
Time: 04:50 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 23.1983" N,  
73° 46' 34.4618" W  
Distance to Tower: 600 Feet



Photo 4 - Granite Springs Road near Hilltop Road, near #54  
PROPOSED CONDITION - 130FT MONOPINE

Photograph Information

Date: April 16, 2021  
Time: 04:50 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 23.1983" N,  
73° 46' 34.4618" W  
Distance to Tower: 600 Feet



Photo 5 - Weatherby St near Castle Ct  
EXISTING CONDITION

Photograph Information

Date: April 16, 2021  
Time: 04:54 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 32.4473" N,  
73° 46' 41.5067" W  
Distance to Tower: 1,100 Feet



Photo 5 - Weatherby St near Castle Ct  
PROPOSED CONDITION - 130FT GALVANIZED TOWER

Photograph Information

Date: April 16, 2021  
Time: 04:54 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 32.4473" N,  
73° 46' 41.5067" W  
Distance to Tower: 1,100 Feet

Figure B14

PHOTO SIMULATIONS

Visual Resource Assessment

New York (NY-578)



Photo 5 - Weatherby St near Castle Ct  
PROPOSED CONDITION - 130FT MONOPINE

Photograph Information

Date: April 16, 2021  
Time: 04:54 PM  
Focal Length: 48 mm  
Camera: Nikon D3500

Photo Location: 41° 18' 32.4473" N,  
73° 46' 41.5067" W  
Distance to Tower: 1,100 Feet