

## KITCHAWAN WATER DISTRICT - LEAD SERVICE LINE INVENTORY

Street Address	Town	Zip Code	Lead Gooseneck, Pigtall or Connector Currently Present?	Current Public Side SL Material ①	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method ①	Public SL Installation or Replacement Date	Public SL Size	Customer SL Material ①	Customer SL Material Verification Method ①	Lead Solder Present?	Building Type	POU or POE Treatment Present? ①	Customer SL Installation or Replacement Date	Customer SL Size	SL Category ①
200 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/7/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/7/2005	Upto 1"	Non-Lead
201 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
202 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
203 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	5/24/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	5/24/2006	Upto 1"	Non-Lead
204 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	8/21/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	8/21/2006	Upto 1"	Non-Lead
205 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	9/18/2008	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	9/18/2008	Upto 1"	Non-Lead
207 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/20/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/20/2005	Upto 1"	Non-Lead
208 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/20/05	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/20/05	Upto 1"	Non-Lead
209 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/4/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/4/2005	Upto 1"	Non-Lead
210 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/19/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/19/2005	Upto 1"	Non-Lead
211 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/19/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/19/2005	Upto 1"	Non-Lead
212 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
213 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	8/21/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	8/21/2006	Upto 1"	Non-Lead
214 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
170 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/2/2005	Upto 1"	Non-Lead
171 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	1/20/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	1/20/2006	Upto 1"	Non-Lead
191 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/28/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/28/2005	Upto 1"	Non-Lead
200 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/2/2005	Upto 1"	Non-Lead
205 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/7/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/7/2005	Upto 1"	Non-Lead
210 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/3/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/3/2005	Upto 1"	Non-Lead
215 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown		Upto 1"	Non-Lead
220 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/31/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/31/2005	Upto 1"	Non-Lead
225 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/21/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/21/2005	Upto 1"	Non-Lead
240 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	3/24/2009	Upto 1"	Copper	Field Inspection	No	Single Family	Unknown	3/24/2009	Upto 1"	Non-Lead
245 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/3/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/3/2005	Upto 1"	Non-Lead
250 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/10/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/10/2006	Upto 1"	Non-Lead
265 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	7/10/2007	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	7/10/2007	Upto 1"	Non-Lead
275 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/27/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/27/2005	Upto 1"	Non-Lead
301 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/23/2006	Upto 1"	Copper	Field Inspection	Yes	r including Mu	Unknown	10/23/2006	Upto 1"	Non-Lead
800 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	4/27/2023	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	4/27/2023	Upto 1"	Non-Lead
801 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	4/5/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	4/5/2006	Upto 1"	Non-Lead
802 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/1/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/1/2005	Upto 1"	Non-Lead
803 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	9/27/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	9/27/2005	Upto 1"	Non-Lead
804 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	7/30/2007	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	7/30/2007	Upto 1"	Non-Lead
805 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/10/2007	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/10/2007	Upto 1"	Non-Lead
806 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	9/12/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	9/12/2006	Upto 1"	Non-Lead
808 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/8/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/8/2005	Upto 1"	Non-Lead
809 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/6/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/6/2005	Upto 1"	Non-Lead
810 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	5/1/2019	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	5/1/2019	Upto 1"	Non-Lead
811 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/26/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/26/2005	Upto 1"	Non-Lead
801 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/14/2021	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	12/14/2021	Upto 1"	Non-Lead
803 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	2/2/2016	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	2/2/2016	Upto 1"	Non-Lead
811 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	7/8/2016	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	7/8/2016	Upto 1"	Non-Lead
812 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	5/28/2020	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	5/28/2020	Upto 1"	Non-Lead
820 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/4/2014	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	12/4/2014	Upto 1"	Non-Lead
822 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/4/2014	Upto 1"	Galvanized	Field Inspection	Yes	Single Family	Unknown	12/4/2014	Upto 1"	Non-Lead
824 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/4/2014	Upto 1"	Galvanized	Field Inspection	Yes	Single Family	Unknown	12/4/2014	Upto 1"	Non-Lead