

Summary of Lead Service Line Inventory

I. System Information

Water System Name	KITCHAWAN WATER DISTRICT
PWS ID Number	NY5903831

II. Contact Information for Owner / Licensed Operator of Record Completing the Form

Contact Name	Ed Lachterman / Paul Vasillo
Contact Phone Number	914-334-5911 / 914-245-6111
Contact Email Address	elachterman@yorktownny.gov / pvasillo@yorktownny.gov

III. Summary of Inventory

Total Number of Service Lines in the Distribution System	47
Total Number of Identified Service Lines	47
Total Number of Lead Service Lines	0
Total Number of GSLRR	0
Total Number of Non-LSL	47
Total Number of Unknown Service Lines	0

Service Lines	Lead	GSL or GSLRR	Non-Lead	Unknown
PWS - Side Service Lines	0	0 GSL	47	0
Customer - Side Service Lines	0	2 GSL	45	0
Total Number of Service Lines in the Distribution System	0	0 GSLRR	47	0

Service Line Identification Methods

Identification Methods	PWS- Side SLs	Customer-Side SLs
Historical Records	0	0
Field Inspection	47	47
Customer Identification with Photo or other Verification	NA	0
Excavation	0	0
Sequential Sampling	0	0
Statistical Analysis/Predictive Model	0	0

IV. Inventory Availability - The inventory must be available to public

If 50,000 customers or greater: Posting the inventory online water system's website. If under 50,000 customers: Explain how to access the inventory	Address: LSL Inventory Posted @ www.yorktownny.gov/water
---	--

V. Certifications

By submitting this form, I have verified and certify the information listed in this form is true and accurate to the best of my knowledge and belief.

Paul Vasillo
Name

Water Distribution Superintendent
Title

10/15/24
Date

KITCHAWAN WATER DISTRICT - LEAD SERVICE LINE INVENTORY

Street Address	Town	Zip Code	Public Side SL Material	Current Public Side SL Material	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method	Public SL Material Size	Customer SL Material	Customer SL Material Verification Method	Lead Status	Building Type	POB or PBE Inspection Date	Customer SL Material Verification Date	SL Category		
200 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/7/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/7/2005	Upto 1"	Non-Lead
201 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
202 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
203 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	5/24/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	5/24/2006	Upto 1"	Non-Lead
204 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	8/21/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	8/21/2006	Upto 1"	Non-Lead
205 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	9/18/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	9/18/2006	Upto 1"	Non-Lead
207 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/20/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/20/2005	Upto 1"	Non-Lead
208 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/20/05	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/20/05	Upto 1"	Non-Lead
209 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/4/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/4/2005	Upto 1"	Non-Lead
210 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/19/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/19/2005	Upto 1"	Non-Lead
211 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/19/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/19/2005	Upto 1"	Non-Lead
212 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
213 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	8/21/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	8/21/2006	Upto 1"	Non-Lead
214 Barnes Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/17/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/17/2005	Upto 1"	Non-Lead
170 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/2/2005	Upto 1"	Non-Lead
171 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/20/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	12/20/2006	Upto 1"	Non-Lead
191 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/28/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/28/2005	Upto 1"	Non-Lead
200 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/2/2005	Upto 1"	Non-Lead
205 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/2/2005	Upto 1"	Non-Lead
210 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/3/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/7/2005	Upto 1"	Non-Lead
215 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/2/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/3/2005	Upto 1"	Non-Lead
220 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/31/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/31/2005	Upto 1"	Non-Lead
225 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/21/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/21/2005	Upto 1"	Non-Lead
240 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	3/24/2009	Upto 1"	Copper	Field Inspection	No	Single Family	Unknown	3/24/2009	Upto 1"	Non-Lead
245 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/3/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/3/2005	Upto 1"	Non-Lead
250 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/10/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/10/2006	Upto 1"	Non-Lead
265 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	7/10/2007	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	7/10/2007	Upto 1"	Non-Lead
275 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/27/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/27/2005	Upto 1"	Non-Lead
301 Chadeayne Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/23/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/23/2006	Upto 1"	Non-Lead
800 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	4/27/2023	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	4/27/2023	Upto 1"	Non-Lead
801 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	4/5/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	4/5/2006	Upto 1"	Non-Lead
802 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/1/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/1/2005	Upto 1"	Non-Lead
803 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	9/27/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	9/27/2005	Upto 1"	Non-Lead
804 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	7/30/2007	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	7/30/2007	Upto 1"	Non-Lead
805 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/10/2007	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/10/2007	Upto 1"	Non-Lead
806 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	9/12/2006	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	9/12/2006	Upto 1"	Non-Lead
808 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	11/8/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	11/8/2005	Upto 1"	Non-Lead
809 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/6/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/6/2005	Upto 1"	Non-Lead
810 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	5/1/2019	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	5/1/2019	Upto 1"	Non-Lead
811 Syska Rd.	Ossining	10562	No	Copper	No	Field Inspection	10/26/2005	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	10/26/2005	Upto 1"	Non-Lead
801 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/14/2021	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	12/14/2021	Upto 1"	Non-Lead
803 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	2/2/2016	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	2/2/2016	Upto 1"	Non-Lead
811 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	7/8/2016	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	7/8/2016	Upto 1"	Non-Lead
812 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	5/28/2020	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	5/28/2020	Upto 1"	Non-Lead
820 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/4/2014	Upto 1"	Copper	Field Inspection	Yes	Single Family	Unknown	12/4/2014	Upto 1"	Non-Lead
822 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/4/2014	Upto 1"	Galvanized	Field Inspection	Yes	Single Family	Unknown	12/4/2014	Upto 1"	Non-Lead
824 Pines Bridge Rd.	Ossining	10562	No	Copper	No	Field Inspection	12/4/2014	Upto 1"	Galvanized	Field Inspection	Yes	Single Family	Unknown	12/4/2014	Upto 1"	Non-Lead